	T5-63 EDITIONS Approved For Refease 2002/10/(16A5SIMTRIARESPRO0404R/0001000	240013-5 KFG. 9-66
	Approved for Release 2002/10/1913518-TAINES 2001/000 1001	240013-5 _{ROUTING}
	DATE TOPSECRET 2	10 [UX
*	$\frac{3}{4}\frac{D}{\phi}$	70 11 D(U)
	5 47	1 13 RB
	TO :	must 14 DISA
	FROM : CHIE	7.5 16
. :	Ar I	IMDITV
**	ACTION:	
	INFO :	
	20-72	
	IN 72530 By 67305A 1-15 BF	25X1A
	Dr. or Signature	
	TO INFO	CITE
	TOPSECRET 060545Z CITE	aus - for au
25X1A	PRIORITY INFO PRIORITY	25X1A CITE please au ein/evaluate au ein/eval
	OXCAPT BLACKSHIELD OPS	t your ten
25X1A	REF:	Col Zalk. 25X1A
25X1A	COL SHELTON AND FROM	25X1A
•	1. REF PAP 1A. WE HAVE NO DOUBTS WHAT SO EVER	THAT 25X1A
•	OPERATED THE PACKAGE IAW PROGRAMMED DATA.	AS MATTER OF FACT
	FILM STRIP AND BRIEFINGS SHOWED TURN ON POINT ONE ME	
	PPEVENT POSSIBILITY OF TURNING ON IN A TURN AS	25X1A
25X1A	TURN-ON POINT WAS AT POLL IN OF TURN.	·
	2. SUSPECT THE CAUSE FOR YOUR CONCERN DUE TO THE	FACT THAT
ULL N	Q-BAY CONTROL WAS ACCIDENTLY TURNED "OFF" SOMETIME A	FIER ENGINE START.
graph.	THIS WAS NOT NOTICED BY PILOT UNTIL JUST PRIOP TO ON	E MINUTE PACKAGE
No.	CHECK AFTER TAKE-OFF AND ENROUTE TO TANKER. THE EXA	
	NOT KNOWN, HOWEVER, WE JUDGED IT TO APPROXIMATELY TE	N MINUTES DURING
	MISSION DEBRIEFING. SUSPECTED CAUSE OF ACCIDENTAL T	URN-OFF WAS P.E.
	PERSONNEL REMOVING PINS OR SUIT CONDITIONING HOSE AF	TEP LEFT ENGINE
	STAPT. WE HAVE TAKEN ACTION TO PREVENT REOCCUPRENCE	
· ·		GROUP I LUDED FROM AUTO- LTIC DOWNERADING D DECLASSIFICATION

REPRODUCTION BY OTHER THAN THE ISSUING OFFICE IS PROHIBITED. COPY NO. Approved For Release 2002/10/16: CIA-RDP69B00404R000100240013-5

25X1A

25X1A

IN 72530 TOPSECRET PAGE 2

EXPECT PROBLEMS WITH DATA CHAMBER IS NOT OPERATING, AND YOU SHOULD EXPECT PROBLEMS WITH DATA CHAMBER CORPELATION. A BETTER METHOD OF DETERMINING THE TUPN ON POSITION ON THIS AND ALL MISSIONS WOULD BE TO USE THE POINT OF INCREASED SCAN RATE ON THE SC&DM.

3. PEF PARA IR.

ON PEVERSE COURSE MISSIONS SUCH AS BSC22B HAS BEEN ADOPTED

AND I TO INCREASE PROGRAMMED FUEL AT KADENA TO 10,000 LRS MIN.

DATA COMPILED AT KADENA HAS SHOWN THE CLIMB DISTANCE IS CONSIDERABLE

LESS THAN THAT DISPLAYED ON COMPUTER FLIGHT PLAN DUE TO EXTREMELY

COLD TEMPERATURES ENCOUNTERED RETWEEN FL400 AND 750. SC&DM FOR

BX6732 SHOWS CLIMB FROM FL294 TO FL781 TO BE 303NM IN LENGTH, AS

COMPAPED TO 345NM AND FL785 ON COMPUTER FLIGHT PLAN. AS YOU CAN

SEE THIS HAS NOT AFFECTED PROGRAMMED OP MINIMUM PENETRATION ALTITUDE

ALTHOUGH THE HEAVY WEIGHT TURN AT START CC DOES, TO SOME DEGREE,

REDUCE OVERFLIGHT ALTITUDE.

- B. IF PRESENT SYSTEM OF COMING BACK UP OUTBOUND TRACK WITH

 TANKER MUST BE DISCONTINUED, I BELIEVE A TUPN AT THE FUEL DECISION

 POINT ABEAM HAINAN ISLAND ON MISSIONS SUCH AS BSC22B WILL BE ROUTING

 TO APPIVE AT KADENA WITH 10,000LBS FUEL REMAINING. FUEL CONSUMPTION

 HAS BEEN INCREASED BY CLIMBING TO FLEDO AFTEP

 AP, BY 25X1

 WARMER THAN STANDARD TEMPERATURES ABOVE FL 75C, BY HEAVY WEIGHT TURNS

 AT START CC. AND BY USE OF FULL AB ON FLIGHT OVER DENIED TERRITORY.
- C. ADDITIONALLY, DESCENT RANGES HAVE BEEN SIMILAPLY AFFECTED BY
 THIS COLD TEMPERATURE AND INSTEAD OF THE CUSTOMARY 225NM DESCENT

TOPSECRET

25X1A

IN 72530	то	P	S	Ε	C	P	E	T	PAGE	3

RANGE, WE HAVE FOUND THAT A MINIMUM DESCENT RANGE OF 260NM MUST RE USED TO BOTTOM OUT 20NM FROM THE APCP. DRIVERS FEEL THAT A DESCENT RANGE OF 275 NM WOULD BE OPTIMUM FOR ASSURING NO OVERSHOOT AT ARCP.

(BX 6732 SC&DM SHOWS DESCENT RANGE TO BE 275 NM FROM START DESCENT TO BOTTOM OUT, 14 NM SHORT OF APCP.)

MANCE AND CHART PERFORMANCE FIGURES ARE NOT ALWAYS THE SAME. CHANGES
IN OUR CLIMB AND DESCENT PANGE ARE A FACT DUE TO THIS EXTREME COLD AIR
BETWEEN FL400 AND 750, EVEN THOUGH COMPUTER AND PERFORMANCE FIGUES
DONT'T SHOW IT. WE HAVE BEEN TAKING ADVANTAGE OF BETTER CLIMB
PERFORMANCE TO GET HOME WITH MORE FUEL.

TOPSECPET TOP: 262642Z NOV 67

don't agree - how the hell can we the true.

gwie flight plan (valid) if the than standard

the were told it was hotter than standard

now it's colder than standard.

TOPSECRET